

FIG. 1A





FIG. 1B







FIG. 4A

Evaluation of Sample Temperature Effects on the PRO LR ACT Assay

Assayed LR ACT cartridge production lot ACT021898

Center line is the mean of all assay values with the 2.S.D. range shown by lines above and below the mean.
Also see Figures 4B and 4C.




FIG. 4B

Blood Heparin Level Adjusted to 1.5 U/ mL




FIG. 4C

Blood Heparin Levels Adjusted to 3.0 U/ mL

